


MONUMENT RECORD
Corner ID: Rich_O11
Section Corner
Section 15- T09N-R02W, 2nd P.M.
Richland Township, Monroe County, Indiana



EXISTING SURVEY HISTORY

Include as much detail and history of the corner as known at the time of perpetuation.

SUBSEQUENT CORNER RESTORATION:

Date Surveyed: *1/28/1999* By: *Kevin P. Enright*

Where filed or recorded: *M.C.S.O. Records*

Original monument: *Pipe*

Bearing Trees or Reference Monuments:

Species	Dia.	Bearing	Distance
<i>Mag in Black Cherry</i>	<i>16"</i>	<i>N 41° E</i>	<i>38.60'</i>
<i>Mag in Hackberry</i>	<i>11"</i>	<i>N 79° E</i>	<i>10.00'</i>
<i>Mag in Beech</i>	<i>31"</i>	<i>S 32° W</i>	<i>42.37'</i>

Notes:

SURVEY EVIDENCE FOUND: Include evidence found and weighed, search area or areas, search procedure, etc.

Date of Search: *11/11/21* By: *J.R. & K.H.* Monument Found: *1" Dia. Iron Pipe*

BTs or Reference Objects Found: *A Wood Post was found Southeast of the corner and is believed to be the fence corner bearing the Monroe County "PROTECT NEARBY SURVEY MARKER" sign shown on the M.C.S.O. 1999 tie sheet. This Wood Post was no longer upright and new sign was placed nearby.* Notes:

OTHER SURVEY HISTORY: Include details such as surveyor name, date, recording info, monument description, etc.

PERPETUATION RECORD

MONUMENT: Describe monument set or found (Include material type, scribing, distance above/below grade, dimensions.)

1" Dia. Iron pipe with hexagonal nut found 5" A.G.

OTHER EVIDENCE: Describe corner location relative to nearby features and how to reach the corner location – note fences, roads, timber cutting lines, mow lines, clearings, plantings, streams, topo changes, etc.

Found at North extension of N-S running wire fence. A tree line runs North from the corner and a brush line runs East from the corner.

THEORY OF LOCATION: Describe the theory of location for acceptance of this monument with reference to the recording information for the survey upon which this record is derived. Said recorded survey shall be certified by the same professional surveyor who certifies this document, shall identify and accept this monument, and shall have been recorded within (3) years of Form submittal.

This pipe was found to be referenced by Monroe County Surveyor Kevin P. Enright on January 28th, 1999 as found in the records of the Monroe County Surveyor's Office. Surveys performed by Kevin Burton Potter and Douglas R. Curry show a wood post with a pipe driven next to it marking this corner. A wood post was found lying on the ground just South of this pipe and is believed by this surveyor to have stood next to the pipe at some point. The pipe was found to be commonly accepted by several other surveys in the area and was accepted and held as said corner.

MONUMENT PRESERVATION: Describe work done to preserve existing monument. Stone mounds should be placed around monuments when stones are readily available. Paint corner stones but not the scribing. A Monroe County "PROTECT NEARBY SURVEY MARKER" sign shall be attached to a steel post when practicable. Note location and relation of corner to sign.

A Monroe County "PROTECT NEARBY SURVEY MARKER" sign was placed on the East side of a 10" Dia. Sugar Maple West of the Corner

GEODETIC COORDINATES: Northing: *1445527.0*, Easting: *3083773.3*

BASIS OF GEODETIC COORDINATES: Describe equipment, date, and personnel used to collect coordinates, datum, epoch, geoid and zone.

Coordinates shown hereon were obtained from GPS observations utilizing the Indiana Real-Time Network (INCORS). Indiana West Zone, NAD83(2011) Epoch 2010.0000, State Plane Grid Coordinates, US Survey Feet. Geoid model G2012BU7. Datum NAD83_NO_TRANS and the use of a Topcon GT Robotic Total Station by Jackson Rogers and Kyle Hazelman on November 11th, 2021.

WITNESS MONUMENT TIES: Describe at least three new BT's and/or witness objects established or work done to preserve existing evidence. The following procedures are provided for guidance. Please utilize professional judgment when choosing witness ties. All ties to BT's should be a magnetic nail and washer (state what kind) set in a hack mark at root crown (less than 12" above ground) perpendicular to center of tree unless otherwise noted. All monuments should be tied to at least three accessories with a minimum of 60° of separation. BTs should be healthy with a minimum DBH of 4". BT description should include tree species, diameter at 4.5' above ground, distance of nail above ground, and description of nail location (e.g.. SE side of root). Note bearing from monument to the center of the BT, distance to the nail. Other survey monuments that were located in the vicinity and their relation to the monument may also be included.

ID	Bearing	Distance	Description
<i>B</i>	<i>S 34° E</i>	<i>15.40'</i>	<i>Chiseled "X" in Northwest side of Manhole rim</i>
<i>C</i>	<i>N 39° E</i>	<i>27.09'</i>	<i>Mag w/ washer set 18" A.G. in West side of 6" Dia. Sycamore</i>
<i>D</i>	<i>N 75° W</i>	<i>12.26'</i>	<i>Mag w/ washer set 12" A.G. in South side of 10" Dia. Sugar Maple</i>


MONUMENT RECORD

Corner ID: Rich_O11

Section Corner

Section 15- T09N-R02W, 2nd P.M.

Richland Township, Monroe County, Indiana



MONUMENT LOCATION SKETCH: Optional: Attach a sketch or aerial image. Monument sketch is not required for reimbursement.

PHOTO IDENTIFIED: Photograph close up photo of monument and a vicinity photo of the monument that includes the Monroe County “PROTECT NEARBY SURVEY MARKER” sign. Provide photo orientation and date. Additional photos may be included by clicking the “+” button at the end of the horizontal line.

Photo Date:



Photo Orientation & Description: *Looking West at O-11*



Photo Orientation & Description: *Looking South at O-11*

FIELD PERSONNEL:

Field Date: *11/11/21* By: *J.R. & K.H.* Project #: *21-157* Field Book: , page: Notes:

CERTIFICATION:

Professional Surveyor Name: *Eric L. Deckard*
Indiana Professional Surveyor No.: *29900012*
Firm Name: *Deckard Land Surveying*
Date: *12/03/21*


Signature:

[Handwritten Signature]






Seal:

MONUMENT RECORD
Corner ID: Rich_O11
Section Corner
Section 15- T09N-R02W, 2nd P.M.
Richland Township, Monroe County, Indiana



NOTICE TO PROCEED AND MONUMENT RECORD FORM ISSUED TO:			
Offeror Name: Eric L. Deckard		Firm Name: Deckard Land Surveying, LLC	
Phone: (812)961-0235		Email: Ericdeckard1@msn.com	
Corner Classification: Section Corner		Corner Coordinate Status: Perpetuated	
Issue Date: 7/12/22	Form Due Date: 7/21/22	Form Receipt Date: 7/21/2022	

COUNTY SURVEYOR APPROVAL:	Seal:
<div><input checked="" type="checkbox"/> Yes, Signature: </div> <div><input type="checkbox"/> No, reasons for denial</div>	

SURVEYOR REVIEW BOARD APPROVAL:	Seal:
<div><input checked="" type="checkbox"/> Yes, Signature: </div> <div><input type="checkbox"/> No, reasons for denial</div>	